

BUHAR BASINÇ KAYBI DİYAGRAMI

bar	0	0.1	0.3	0.5	1.0	1.5	2.0	2.5	4.0	5.0	6.0	7.0	7.5	8.5	10.0	12.0	14.0	15.0	17.0	20.0	24.0	28.0	34.0	42.0
factor	6.9	6.39	5.47	4.79	3.67	2.97	2.51	2.17	1.55	1.31	1.13	1.0	0.94	0.85	0.74	0.63	0.55	0.52	0.46	0.39	0.33	0.29	0.24	0.19

